PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref :

Date : 19.6.2014

YIELD REPORT

1. Name and Address of the Party : AEE Ward No 14 Dasarahalli Sub Division B.B.M.P.
2. Borewell Location : Royal Enclave.
3. Total Depth Drilled : 1049 Feet
4. Casing Pipe : 164 Feet
5. Coupling : 9 coupling
6. Yield Details :
   a) First Spring Touched at : 280 Feet
   b) Second Spring Touched at : 490 Feet
   c) Third Spring Touched at : 890 Feet
7. Total Yield in G.P.H. : 1200 GPH
8. Remarks : Yield's Good

For PALLAVI BOREWELL & DRILLERS

M B Nagaraj
Proprietor

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref :

Date : ....19..6..2014..

YIELD REPORT

1. Name and Address of the Party : AEE Ward NO-14 Dasarahalli Sub Division BBMP.
2. Borewell Location : Soap factory Layout
3. Total Depth Drilled : 1049 Feet
4. Casing Pipe : 164 Feet
5. Coupling : 9 couply
6. Yield Details :
   a) First Spring Touched at : 415 Feet
   b) Second Spring Touched at : 730 Feet
   c) Third Spring Touched at : 850 Feet
7. Total Yield in G.P.H. : 1200 GPH
8. Remarks : Yield Good

For PALLAVI BOREWELL & DRILLERS

M. B. Manjunath
Proprietor

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

1st print:- ✓

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

To the Assistant Executive Engineer
BBMP
Dasarahalli Sub Division
Royal Enclave

Date : 15.6.2014

1. Name of the Customer — Ward No:-14
2. a) Village — 3rd cross — b) Block / Taluk. — c) District Bangalore
3. Location.
4. Lithology of the Area — Granetic | Laterite in nature
5. Tophographic Features of the Area — The area was plain land
6. Hydrogeological condition of the Area — Good
7. Geophysical survey result. — By Division method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 30ft 9 } 2
      180-520' }
      650-680' } 2
      NB-14
   e) Condition of Ground Water. — Good
8. Type of well Recommended. — Cased (6½") -
9. Depth Recommended. — 650-700' -
10. Expected Yield. — 1400-1500 GPH
11. Quality of Water. — Good -
12. Approximate depth at which the water is expected to be met. — Around 30ft 9
13. Recommended Type and Length of casing to be inserted. — nearly 80-100' NS casing may be needed
14. Rain water Harvesting adviced or not — Strictly Adviced -
15. Remarks.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Recommended point for Drilling

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

11th permit :-

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

To the Asst Executive Engineer
BBMP
Dasarahalli Sub Division

Date : 15-6-2014

1. Name of the Customer
2. Location.
   a) Village Ward No: 14 3rd cross Road b) Block / Taluk. Soap factory rapid c) District Bangalore
3. Lithology of the Area — Gravelly / sandy in nature
4. Tophographic Features of the Area — The area was a plain land
5. Hydrogeological condition of the Area — Good
6. Geophysical survey result. — By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 500'9
      780 - 800'
      1020 - 1060'
      2
      2
   e) Condition of Ground Water. — Good
7. Type of well Recommended. — Bore well (6½")
8. Depth Recommended. — 1050 - 1100'
9. Expected Yield. — 1400 - 1600 GPH
10. Quality of Water. — Good
11. Approximate depth at which the water is expected to be met. — Around 500'9
12. Recommended Type and Length of casing to be inserted. — Nearly 140 - 160' of MS Casing may be needed
13. Rain water Harvesting adviced or not — Strictly Adviced
14. Remarks.



Site Plan Map

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.